10/088,918



In the United States Patent and Trademark Office

6,892,691 BV Patent No:

Group Art Unit: 3747

S. Uhl et al Inventors:

Examiner: John T. Kwon

Issued: May 17, 2005

Attorney Docket: R 36311

For: Method for Operating an

Internal Combustion Engine

Certificate JUN 0 6 2005 of Correction

Request for Certificate of Correction Pursuant to 37 CFR 1.322

Commissioner for Patents and Trademarks P.O. Box 1450 Alexandria, Virginia 22313-1450

Attention:

Decision and Certificate of Correction

Branch of the Patent Issue Division

Dear Sir:

Transmitted herewith is a proposed certificate of correction for United States Patent 6,892,691 issued on May 17, 2005.

Printing errors occurred in the patent which should be corrected as follows:

In column 6:

Line 44: delete "mother" and substitute -- motor -- therefor.

On behalf of the inventors and the assignee of record, Robert Bosch GmbH, it is respectfully requested that the certificate of correction be approved pursuant to 37 CFR 1.322 and that an approved

copy thereof be sent to the attorney of record at the address shown below.

Respectfully submitted,

Walter Ottesen Reg. No. 25,544

Walter Ottesen Patent Attorney P.O. Box 4026 Gaithersburg, Maryland 20885-4026

Phone: (301) 869-8950

Date: May 27, 2005

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 6,892,691 β (DATED : May 17, 2005

INVENTOR(S): Stephan Uhl and Andreas Roth

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 6:

Line 44: delete "mother" and substitute -- motor -therefor.

MAILING ADDRESS OF SENDER:

Walter Ottesen **Patent Attorney** P.O. Box 4026 Gaithersburg, Maryland 20885-4026 PATENT NO. 6,892,691 B1 No. of add'l. copies @ 30c per page

FORM PTO 1050 (REV. 3-82)